

Belzona Repairs Concrete Footing

ID: 7564

Industry: *Building & Structures*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Concrete and Steel Reinforcement*
Products: *Belzona® 4111 (Magma Quartz)*

Customer Location: *Construction company, Slovakia*
Application Date: *2006*

Problem

The footing was damaged by impact, this caused instability on the machine which meant it could not be used.



Photograph Descriptions

1. Destroyed concrete footing
2. Belzona® 4911 (TX Conditioner) application
3. Repair in progress
4. Belzona® 4111 used to rebuild the base

Application Situation

The concrete footing of a cutting machine in a large workshop.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

The Belzona concrete repair allowed the machinery to be back online in only 4 days, compared to the possible 28 days cure time for concrete. The Belzona materials also have greater impact resistance to protect from future damage.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve